


## Socket grub screws with 6 lobe drive ~ DIN 913



### Details du produit

#### Description

Grub screws, also known as set screws, are ideal for securing two components together without the use of a nut. They also produce an un-obtrusive fastening with no head to protrude above the surface.This grub screw has a torx type drive socket.

#### Advantages

Sits fully inside the threaded hole hidden from view. This also means that this type of screw will take more torque as it is fully supported.

#### Qualities

Resistant to corrosion and many other external contaminants.

#### usage

Used in all industrial activity as a hidden screw or locking screw among other varied uses.

| d   | L    | T  | Minimum sales Quantity | SKU        |
|-----|------|----|------------------------|------------|
| M10 | 10,0 | 30 | 5000                   | 9131010TXA |
| M10 | 12,0 | 30 | 5000                   | 9131012TXA |
| M10 | 16,0 | 30 | 5000                   | 9131016TXA |
| M10 | 20,0 | 30 | 5000                   | 9131020TXA |
| M10 | 25,0 | 30 | 5000                   | 9131025TXA |
| M10 | 30,0 | 30 | 5000                   | 9131030TXA |
| M10 | 35,0 | 30 | 5000                   | 9131035TXA |

| d   | L    | T  | Minimum sales Quantity | SKU        |
|-----|------|----|------------------------|------------|
| M10 | 40,0 | 30 | 5000                   | 9131040TXA |
| M10 | 45,0 | 30 | 5000                   | 9131045TXA |
| M10 | 50,0 | 30 | 5000                   | 9131050TXA |
| M10 | 6,0  | 30 | 5000                   | 913106TXA  |
| M10 | 8,0  | 30 | 5000                   | 913108TXA  |
| M12 | 10,0 | 40 | 5000                   | 9131210TXA |
| M12 | 12,0 | 40 | 5000                   | 9131212TXA |
| M12 | 16,0 | 40 | 5000                   | 9131216TXA |
| M12 | 20,0 | 40 | 5000                   | 9131220TXA |
| M12 | 25,0 | 40 | 5000                   | 9131225TXA |
| M12 | 30,0 | 40 | 5000                   | 9131230TXA |
| M12 | 35,0 | 40 | 5000                   | 9131235TXA |
| M12 | 40,0 | 40 | 5000                   | 9131240TXA |
| M12 | 45,0 | 40 | 5000                   | 9131245TXA |
| M12 | 50,0 | 40 | 5000                   | 9131250TXA |
| M4  | 10,0 | 8  | 5000                   | 913410TXA  |
| M4  | 12,0 | 8  | 5000                   | 913412TXA  |
| M4  | 16,0 | 8  | 5000                   | 913416TXA  |
| M4  | 20,0 | 8  | 5000                   | 913420TXA  |
| M4  | 25,0 | 8  | 5000                   | 913425TXA  |
| M4  | 6,0  | 8  | 5000                   | 91346TXA   |

| d  | L    | T  | Minimum sales Quantity | SKU       |
|----|------|----|------------------------|-----------|
| M4 | 8,0  | 8  | 5000                   | 91348TXA  |
| M5 | 10,0 | 10 | 5000                   | 913510TXA |
| M5 | 12,0 | 10 | 5000                   | 913512TXA |
| M5 | 16,0 | 10 | 5000                   | 913516TXA |
| M5 | 20,0 | 10 | 5000                   | 913520TXA |
| M5 | 25,0 | 10 | 5000                   | 913525TXA |
| M5 | 30,0 | 10 | 5000                   | 913530TXA |
| M5 | 35,0 | 10 | 5000                   | 913535TXA |
| M5 | 40,0 | 10 | 5000                   | 913540TXA |
| M5 | 45,0 | 10 | 5000                   | 913545TXA |
| M5 | 50,0 | 10 | 5000                   | 913550TXA |
| M5 | 6,0  | 10 | 5000                   | 91356TXA  |
| M5 | 8,0  | 10 | 5000                   | 91358TXA  |
| M6 | 10,0 | 15 | 5000                   | 913610TXA |
| M6 | 12,0 | 15 | 5000                   | 913612TXA |
| M6 | 16,0 | 15 | 5000                   | 913616TXA |
| M6 | 20,0 | 15 | 5000                   | 913620TXA |
| M6 | 25,0 | 15 | 5000                   | 913625TXA |
| M6 | 30,0 | 15 | 5000                   | 913630TXA |
| M6 | 35,0 | 15 | 5000                   | 913635TXA |
| M6 | 40,0 | 15 | 5000                   | 913640TXA |

| d  | L    | T  | Minimum sales Quantity | SKU       |
|----|------|----|------------------------|-----------|
| M6 | 45,0 | 15 | 5000                   | 913645TXA |
| M6 | 50,0 | 15 | 5000                   | 913650TXA |
| M6 | 6,0  | 15 | 5000                   | 91366TXA  |
| M6 | 8,0  | 15 | 5000                   | 91368TXA  |
| M8 | 10,0 | 25 | 5000                   | 913810TXA |
| M8 | 12,0 | 25 | 5000                   | 913812TXA |
| M8 | 16,0 | 25 | 5000                   | 913816TXA |
| M8 | 20,0 | 25 | 5000                   | 913820TXA |
| M8 | 25,0 | 25 | 5000                   | 913825TXA |
| M8 | 30,0 | 25 | 5000                   | 913830TXA |
| M8 | 35,0 | 25 | 5000                   | 913835TXA |
| M8 | 40,0 | 25 | 5000                   | 913840TXA |
| M8 | 45,0 | 25 | 5000                   | 913845TXA |
| M8 | 50,0 | 25 | 5000                   | 913850TXA |
| M8 | 6,0  | 25 | 5000                   | 91386TXA  |
| M8 | 8,0  | 25 | 5000                   | 91388TXA  |



**Bülte England**  
37B Basepoint Centre Harts Farm Way Havant Hampshire PO9 1HS